23

Inspection Details

Number of Trees 0 **Date of Inspection** 03/09/2015

Name nagabushan **Remarks**

Any Other Information

Category	Image	Photo Remark
Road Condition		
Segment End		
Segment Start		

AE

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0181

Date: 27/08/2016 Time: 13:09:02 RI 20160827130902

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0182	NA	Near muneswara temple road (alada mara)
Unique Road No.	**Length of full Road(m)**	
13-W0182-10306	67.00	

Road Details

Road From	Road To
Near muneswara temple road (alada mara)2nd cross	Mallikarjuna temple road
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
75.00	4.50			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

☐ Left

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	75.00	0.60

☐ Right

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	75.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		6.20	1.20
RCC deck slab		5.60	2.00

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	2
Others			

Inspection Details

Number of Trees 0 **Date of Inspection** 03/09/2015

Name nagabushan **Remarks**

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0182

Date: 27/08/2016 Time: 13:10:26 RI 20160827131026

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0179	1st Main Rd	Pipeline
Unique Road No.	**Length of full Road(m)**	
13-W0179-10322	33.00	

Road Details

Road From	Road To
Pipeline	mallikarjuna temple road
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
76.00	5.40			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

18

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	76.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	76.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		3.60	1.80

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	2
Others			

AG

17

Inspection Details

Number of Trees 0 **Date of Inspection** 17/07/2015

Name nagabhushan **Remarks**

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0179

Date: 27/08/2016 Time: 13:11:37 RI 20160827131137

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0177	NA	pipeline
Unique Road No.	**Length of full Road(m)**	
13-W0177-10326	25.00	

Road Details

Road From	Road To
Pipeline	Mallikarjuna temple
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
64.00	5.20			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

15

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	64.00	5.20

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		North

Other Flow Direction Type	Length (m)	Average Width(m)
	64.00	5.20

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		5.40	1.50

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	1
Others			

(14)

Inspection Details

Number of Trees 0 **Date of Inspection** 17/07/2015

Name nagabhushan **Remarks**

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.